

# Memorandum

Date : July 15, 2004

o : Edward C. Anton, Chief  
Division of Water Rights  
State Water Resources Control Board  
Post Office Box 100  
Sacramento, California 95812-0100

From : Department of Water Resources

Subject : Suisun Marsh Salinity Control Gate Salmon Passage Study

Attached is the 2003 above-referenced report for your information. The report summarizes the testing and findings of the Department of Water Resources' and the U.S. Bureau of Reclamation's ongoing study of Chinook salmon passage through the Suisun Marsh Salinity Control Gates on Montezuma Slough.

Your receipt of this report complies with the State Water Resources Control Board's previous approvals of your requests for a variance from the electrical conductivity objectives at water quality compliance stations C-2, S-64, S-49, S-42, and S-2 in the Suisun Marsh for the purpose of conducting the study during the period of October 2001 through May 2004.

If you have any questions or need further information, please contact me or your staff may contact Jim Long, Environmental Scientist with the Environmental Site Assessment Branch of the Division of Environmental Services at (916) 445-6360 or via e-mail at [jlong@water.ca.gov](mailto:jlong@water.ca.gov).

*Terry J. Mills*  
Barbara McDonnell, Chief  
Division of Environmental Services  
(916) 227-7531

Attachment

cc: (See attached list)

Victor Pacheco, Chief ✓  
Environmental Planning and  
Information Branch  
Division of Environmental Services  
Department of Water Resources  
3251 S Street  
Sacramento, California 95816

Art Hinojosa  
Operations Compliance and  
Studies Section  
Division of Operations and Maintenance  
Department of Water Resources  
3310 El Camino Avenue  
Sacramento, California 95821

Alan Ng  
Operations Compliance and  
Studies Section  
Division of Operations and Maintenance  
Department of Water Resources  
3310 El Camino Avenue  
Sacramento, California 95821